



**de** Montageanleitung  
**en** Mounting instructions  
**fr** Instructions de montage  
**sv** Monteringsinstruktion  
**nl** Montage-aanwijzing  
**it** Istruzioni di montaggio  
**fi** Asennusohje  
**es** Instrucciones de montaje  
**da** Monteringsvejledning

**Differenzdruckfühler**  
**Differential Pressure Sensors**  
**Sonde de pression différentielle**  
**Differenstryckgivare**  
**Drukverschilopnemer**  
**Sonda di pressione differenziale**  
**Paine-eroanturit**  
**Sondas de diferencia de presión**  
**Trykdifferensføler**


**QBM2030-..**  
**QBM3020-..**





DC 13.5...33 V  
AC 24 ±15%  
DC 0...10 V

1910z12




max. 1.5 mm<sup>2</sup>



1910z13


## Zero Reset

1.




1910z15

2.




1910z14

3.




1910z16

## QBM2030



DIP Switch	QBM2030-1U	QBM2030-5	QBM2030-30
	100 Pa	500 Pa	0...3000 Pa
	+/- 100 Pa	250 Pa	0...1500 Pa
	+/- 50 Pa	200 Pa	0...1000 Pa



## QBM3020




1916Z06

DIP Switch

QBM3020-...



For additional information please refer to the following documents on the Internet:



<http://siemens.com/bt/download>

→ search for "QBM2030" or "QBM3020"